

Mon No	Description	51
41	1/4 corner, Sec. 10/Sec. 15 - Found B.L.M. brass cap, 1963; fits G.L.O. notes.	1/4 corner, Sec. 16/Sec. 15 - Found B.L.M. brass cap, 1963; fits G.L.O. notes.
42	W.C. for E 1/6 corner, Sec. 10/Sec. 15 - Set from which an 11" cedar scribed "W.C. E 1/6 S. 10 B. J." bears N. 44° E., 18.05 ft. and an 11.5" cedar scribed "W.C. E 1/6 S. 15 B. J." bears S. 50° W., 47.25 ft. The E 1/6 Sec. 10/Sec. 15 falls on roadway N. 89° 26' 04" W., 22.47 ft from witness corner.	C-W 1/6 corner, Sec. 15 - Set from which a 10" cedar scribed "C-W 1/6 S. 15, B. J." bears N. 20° W., 25.10 ft. and a 12.5" cedar similarly scribed bears N. 4° E., 29.55 ft.
43	Corner of Sec. 10/Sec. 11/Sec. 14/Sec. 15 - found B.L.M. brass cap, 1963; fits G.L.O. notes.	1/4 corner, Sec. 15/Sec. 14 - inundated by Union Valley Reservoir. Position established from the N.E. cor of Sec. 15 at rec. dist. rotated 00° 58' 09" right which is the mean rotation of all monuments set per 1-3-1-67 that were tied by this survey.
44	1/4 corner, Sec. 11/Sec. 14 - found iron pin with 3" brass cap stamped "R.C.E. 5438, 1959".	SE 1/6, Sec. 16 - Set from which a 15" fir scribed "SE 1/6 S. 16 B. J." bears S. 85° W., 40.0 ft. and a 14" pine similarly scribed bears N. 51° E., 23.20 ft.
45	Corner of Sec. 11/Sec. 12/Sec. 13/Sec. 14 - found B.L.M. brass cap, 1963; fits G.L.O. notes.	S 1/6 corner, Sec. 16/Sec. 15 - Set from which a 12" fir scribed "S 1/6 S. 16 B. J." bears S. 76° W., 8.45 ft. and a 6" fir similarly scribed bears S. 64° E., 26.05 ft.
46	C-N 1/6, Sec. 15 - Set from which a 9.5" fir scribed "C-N 1/6 S. 15 B. J." bears N. 34° W., 7.95 ft. and an 8.5" fir similarly scribed bears N. 81° E., 14.35 feet.	1/4 corner, Sec. 16/Sec. 21 - found B.L.M. brass cap, 1963; fits G.L.O. notes.
47	NE 1/6 corner, Sec. 15 - Set from which a 13" cedar scribed "NE 1/6, S. 15, B. J." bears S. 15° E., 23.4 ft. and a 6.5" fir similarly scribed bears N. 18° E., 18.6 ft.	E 1/6 corner, Sec. 16/Sec. 21 - inundated by Union Valley Reservoir. Found iron pin with 2 1/6" brass disc stamped "W.C.R. R.C.E. 5438, 1963" on line between E 1/6, S 1/6, Sec. 21 and SE 1/6, Sec. 21 985.59 feet from calculated position Sec. 16.
48	C-S-N 1/4 corner, Sec. 15 - Set from which a 12.5 cedar scribed "1/64 S. 15 B. J." bears N. 76° E., 10.2 ft. and a 10" cedar similarly scribed bears S. 80° W., 20.9 ft.	Corner of Sec. 15/Sec. 16/Sec. 21/Sec. 22 - found B.L.M. brass cap, 1963; fits G.L.O. notes.
49	C-S-N 1/4 corner, Sec. 15 - Set from which a 12.5" fir scribed "1/64 S. 15 B. J." bears S. 40° W., 27.20 ft. and a 25" pine similarly scribed bears S. 62° E., 26.55 ft.	1/4 corner, Sec. 15/Sec. 22 - inundated by Union Valley Reservoir. Position established from the S.W. cor Sec. 15 as 72 rods 53 above
50	1/4 corner, Sec. 17/Sec. 16 - found iron pin with 1 1/2" brass cap stamped "R.C.E. 5438, 1959. Corner is 4" below ground, as was rock mound. Reset rocks on surface.	

<p>Note:</p> <ul style="list-style-type: none"> <li>Set 2" aluminum pipe with 3 1/4" aluminum cap stamped for corner T.S. 4598, 1960 in mound of rock.</li> </ul> <p>All rock mounds set and bearing trees scribed, this survey unless otherwise noted.</p> <p><b>RECORD of SURVEY</b></p> <p>Section 33, 3, 13 N., R. 14 E., and Sections 4, 10, 11, 15 and 16, 3, 12 N., R. 14 E., N. D. M.</p> <p>County of El Dorado, State of California</p> <p>Surveyed for the U.S. Forest Service by Michael S. Martin, L.S. 4598</p> <p>Record of Surveys Book 10, Page 850</p> <p>Date April 15, 1982</p>	<p>Sheet 5 of 5</p>
---	---------------------