


# CORNER RECORD

BK 52 PG 52  
Document Number CR 5423

City of Oakland

County of Alameda, California

Brief Legal Description Pin Monument on Darnby Dr @ Longwalk Dr.



## CORNER TYPE

Government Corner ☐ Control ☐  
Meander ☐ Property ☐  
Rancho ☐ Other ☒

Date of Survey 10/09/2012

## COORDINATES (Optional)

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ NAD27 ☐ NAD83 ☐  
NAD83 Epoch \_\_\_\_\_  
Elev. \_\_\_\_\_  
Vert. Datum: NGVD29 ☐ NAVD88 ☐  
Meas. Units: Metric ☐ Imperial ☐

Corner - Left as found ☒ Found and tagged ☐ Established ☐ Reestablished ☐ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

City of Oakland pin monument in standard casting.

See pg 2 for drawing

In compliance with section 8771 of the PLS Act, this corner record is being filed PRIOR to PG & E's underground installations on Darnby Drive.

A description of the physical condition of the monument as found and as set or reset:

The monument was found in good condition.

Ref: City of Oakland Mon Tie Bk 22 pg 34

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyor's Act on 19 July 2013

Signed \_\_\_\_\_

P.L.S or R.C.E. No. 4700

## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received \_\_\_\_\_

and examined and filed \_\_\_\_\_

Signed \_\_\_\_\_

P.L.S or R.C.E. No. 5726

Title \_\_\_\_\_

County Surveyor's Comment: \_\_\_\_\_

